

FIG. 1






FIG. 2



- 14 **16(1)** 14 10 10 -16(2) 18 . 12 = Modified metal 1 18 16(3) 18 14' 10ر -18 ,14 16(4) **L**14 12-

FIG. 4



4/5




FIG. 6a




FIG. 6b




FIG. 7